

# ENDURA SUPPLY

## Pieper Product List

- Part No: 0188-42214-1-001
- Part No: 2041114
- Part No: 2470510HK
- Part No: AM-6.
- Part No: ASZ-800-208-700
- Part No: FK-CF-PTZ-3612-2- IQ-R1 OBSOLETE-replaced by FK-CF-3712-2-78-IQ
- Part No: FK-CF-PTZ-3612-2- IQ-R1-N
- Part No: FK-FC-1024-2-IQ-R1
- Part No: FK-N-CF-1313-2-IQ
- Part No: FK-N-CM-1313-2-IQ
- Part No: FKS-1401-180
- Part No: FRM-208-720
- Part No: FRM-R-208-720-2R
- Part No: FRO-MP-9412-78-HT
- Part No: FRO-R-7070-12
- Part No: FS-1000
- Part No: GASKET (FOR ASZ 800)
- Part No: HG-99-3.0-150
- Part No: IKS-ES-3612-XXX-FRO-MP
- Part No: IPC- H2-1-B-VT
- Part No: IPC -L1-FVT-0203TXFC
- Part No: KMF-850-01
- Part No: RFO-76755921-01
- Part No: SAS-10-10 (10 pin female connector for FS 1000 Net weight (kg) 0,05)
- Part No: SLOT 1: IC1
- Part No: SLOT 2: PLB 1977
- Part No: SLOT 4: PANCON 100-932-433
- Part No: SO-3700-W software package for set-up menu
- Part No: TBM-051
- Part No: TYP: FK-CF-PTZ-3612-2-IQ-R1
- Part No: UBS-FRS-3612
- Part No: VGD 15-ER-S-5.

- Part No: WAH-2180-E
- Part No: WUS-1700-2-M-RJ45
- Part No: WUW-3500-E-LT
- Part No: ZAA-800-2000-2
- Part No: FK-CF-PTZ-3612-2-IQ-R1(85253090) obsolete/replaced by FK-CF-3712-2-78-IQ 1/2" DSP-COLOR-FURNACE CCD
- Part No: FRO-7660-38-78-HT-A AXIAL PROBE LENS
- Part No: FRS-208-550 FURNACE PROBE
- Part No: HT-22-5-2.0-1000 Heat Protecting Filter
- Part No: KMF-853-0 CONNECTION BOX
- Part No: FK-CF-3712-2-78-IQ
- Part No: FRO-5140-38-78-HG-HT-IR-A 1/2" AUTO Aris
- Part No: FRS-208-720
- Part No: FRO-6851-13-78-HG-A DC 1/3a <sup>TM</sup>a <sup>TM</sup>
- Part No: 4090394
- Part No: SO-3700-W Software Package for Set-up Menu of FK-C/M-3700 series Computer Configuration
- Part No: WUW-4500-E-HT
- Part No: FRO-5140-38-78-HG-HT-A
- Part No: NKS-800
- Part No: FRO-3830-38-78-HG-HT-A
- Part No: OFR-M-7805-17
- Part No: HT-22.5.02.0-1000
- Part No: HG-22.5-2.0-900
- Part No: WUW-3627-76-150-E
- Part No: WEF-6000-E.
- Part No: SAS 10 10
- Part No: TUBUS-WUW-3627-89-100-HG-HT
- Part No: HG-11.9-2.5-900
- Part No: KSW-RSXXX-BUS
- Part No: KMF-853-0-SNK-853-12V
- Part No: 1.0-6.6-PVC
- Part No: FRO-5140-38-78-HG-IR-A
- Part No: IM-CT-4819-3-IQ (obsolete - replaced by IM-CT-4826-3-IQ)
- Part No: VMF-187-187(optional)
- Part No: KFP-187 (optional)

- Part No: TBM-051 (optional)
- Part No: DMW-7660 (optional)
- Part No: IKS-3612
- Part No: FRS-V-208-720-550
- Part No: DOC-01 (optional)
- Part No: VP-05(optional)
- Part No: UZ-1 (optional).
- Part No: IM-CT-4317-3-IQ (obsolete - replaced by IM-CT-4318-3-IQ)
- Part No: IM-CT-4318-3-IQ
- Part No: IM-CT-4826-3-IQ
- Part No: UZ-1
- Part No: WUW-3627
- Part No: HT-39-2.0-1000-DMW
- Part No: KMF-850-0
- Part No: B-853-0
- Part No: HT-99-3.0-1000
- Part No: FRO-9881-78-HT-M
- Part No: CK-CF-PTK-3612-2-IQ-RI obsolete / replaced by FK-CF-3712-2-78-IQ
- Part No: SO-3700-W
- Part No: FRM-208-720-2R
- Part No: FRO-7660-38-78-HT- A
- Part No: FR0-3830-38-58-HG-HT-A
- Part No: FRO-1112-78-HT
- Part No: FK-CF-3712-2-78-IQ-N
- Part No: KMF-853- 0
- Part No: FK-CM-6313-2-IQ
- Part No: FK-C3713-2-IQ
- Part No: FK-HD-N-CM-6030-IQ-IPCH2R
- Part No: 204 1114 obsolete, alternative 2214-05354
- Part No: 2214-05354