

ENDURA SUPPLY

POWERNET Product List

- Part No: ADC5483P
- Part No: ADC5423
- Part No: MSR7110/48
- Part No: ADC7180R/48
- Part No: ADC5483
- Part No: ADC7180/24 obsolete, replacement ADC7180R/24
- Part No: ADC 7520/24
- Part No: ADC7180R/24
- Part No: BPU69130VF/21 OEM
- Part No: DAC62132VF/21 OEM
- Part No: ADA7442
- Part No: 230/115VAC/27.4VDC 10A DIN, PFC
- Part No: ADC5423R obsolete / replaced by ADC5483R
- Part No: ADC5483R
- Part No: ADC 4210 discontinued, alternative standard ADC4370/36
- Part No: ADC4370/36
- Part No: SPS4700
- Part No: ADC7480/48H
- Part No: ADC4370/72AI
- Part No: MSR7170/48
- Part No: 70130753
- Part No: ADC7480Multi
- Part No: ADC 7520/24H
- Part No: ADC4370/36-1
- Part No: ADC4370/48AI-2
- Part No: ADC4370/24 T
- Part No: ADC5623
- Part No: ADC4370.02/24 TH-2
- Part No: ADC8220/22 oem
- Part No: ADC7180R/36
- Part No: ADC5483 21...29 VDC
- Part No: 8750230A

- Part No: ADC4370/24H-3
- Part No: P/N:ADC8230R; Type:18-40VAC/25VDC 375W
- Part No: SPS4590
- Part No: ADC4370/96AI
- Part No: ADC5000
- Part No: ADC4370/72AI-1
- Part No: old code ADC5623-4 new code ADC5623
- Part No: ADC5283R
- Part No: ADC5423-1 - old code; ADC5423 - new code
- Part No: ADC5483P-2 - old code; ADC5483P - new code
- Part No: ADC7480/160
- Part No: ADC7480/160T
- Part No: old code ADC4370/24TH-1, new code ADC4370/24 TH-3
- Part No: ADC4370/24TH-3
- Part No: ADC5583
- Part No: ADC5121R
- Part No: ADC5421R
- Part No: ADC5823
- Part No: ADC5083
- Part No: ADC5183
- Part No: ADC5183R
- Part No: ADC7480/24AI
- Part No: ADC5383
- Part No: ADC4370/72A-1
- Part No: ADC7180R/AGC-6
- Part No: 55091500
- Part No: ADC 4370/24H-1
- Part No: ADC7480/110
- Part No: ADC7480/72
- Part No: ADC4370/24TH-2
- Part No: ADC8220/22-2.1 OEM
- Part No: ADC5921/22-0 OEM
- Part No: ADC8440
- Part No: ADC5521
- Part No: ADC7181R/96

- Part No: ADC7181R/24
- Part No: PSU ADC 5523
- Part No: ADC7520R/24