

# ENDURA SUPPLY

## Olaer (Parker) Product List

- Part No: EHV 50-330/90
- Part No: 10865401125
- Part No: 10865701125
- Part No: 108661-01125 SB 330-4,OA1/112U-330A, BAUGLEICH MIT IHV 4-350/90;REF.108661-
- Part No: 10866601125
- Part No: 109847-01125
- Part No: 19029000225
- Part No: 19054200225
- Part No: BLADDER (SPARE FOR ITEM 1) – COMPLETE
- Part No: ECA12-01-L-N
- Part No: EHV 10-330 Ø22
- Part No: EHV 10-350/90/L
- Part No: Typ EHV 1-350/90 old version / new version 1720176 1-350/00
- Part No: PARKER2197
- Part No: EHV 50?330 D22 SPARE KIT
- Part No: 1720034
- Part No: EHV-32-330
- Part No: 1720043
- Part No: 10837301125
- Part No: K508458
- Part No: K508460
- Part No: PARKER541
- Part No: PWO B10-20
- Part No: B120T-70 (Anschlüsse: 2 x G 1 1/2" Innengewinde 2 x G 1 1/4" Innengewinde Mit Gewindebolzen Ref : 05T0484)
- Part No: PWO-B45-60 - OBSOLETE, REPLACEMENT B120T-60
- Part No: OD30191
- Part No: VGU/F. 25/250.7.TS3.3
- Part No: PWO 20-40-B-0-AG-N
- Part No: B5T-10 (Anschlüsse: 2 x G 3/4" Innengewinde 2 x G 1/2" Innengewinde)
- Part No: 1720124
- Part No: LHC-044-A-00-S50-0-0 (Öl/Luftkühler)

- Part No: P/N: 108370-01125 Type: EHV 10-330/90 K old code / new code EHV 10-330/90-A25GA-200 10837001125
- Part No: Gasfüllung 36 bar
- Part No: P/N: 5849016601 Type: LOC3-016-4-D-D-0-00-000-0-0-0-0
- Part No: 10837201125
- Part No: 19032100225
- Part No: PN 19029100225
- Part No: 2003F-02-201 D1
- Part No: 2003F-02-201 D5
- Part No: 2003F-02-201 E1
- Part No: 2003F-02-201 E2
- Part No: 2003F-02-201 E4
- Part No: P/N: 20138102121 Type: VG3.10.1.TS2.1
- Part No: 20214122823 / VGU/F.25/250.8.TS2.3
- Part No: CONNECTOR MG 2-F G ½ BSP ITEM 21 for IHV 37-390
- Part No: CONNECTOR MG 2-F G ½ BSP ITEM 21 for IHV 50-330
- Part No: P/N: 042785011S1 Type: SBV2 ACCU 1-40/13
- Part No: P/N: 202182-07733, Type: VG U-250-TS3
- Part No: Blase 2,5 l ø 22 VL für EHV 2,5-350/90
- Part No: Blase 10 l ø 22 VL für EHV 10-350/90-L
- Part No: 10866201125
- Part No: Blase 475 l ø 63 VL
- Part No: 10234200220I
- Part No: EHV 20-330/90
- Part No: 10010000220
- Part No: 10847901626
- Part No: IHV 10 330/.. GD-L old reference, new reference P/N: 108459-01125 Type: EHV 10-350/90-L-DA
- Part No: EHV 10-350/90-L-DA not available/alternative P/N: 10845901125 Type: EHV 10-350/90-A25EC-200
- Part No: P/N: 10845901125 Type: EHV 10L-350/90/DA
- Part No: 19054100225 \ EHV 50-330 DIA22
- Part No: P/N: 637055V2205 Type: DS307/SCH/V2/5-55/SL/C5
- Part No: P/N: 10845901125 Type: EHV 10-350/90-A25EC-200
- Part No: IBV 475-8/90
- Part No: EHV 32-330/90-01125

- Part No: B190447/00220 obsolete
- Part No: LOC3-007-4-D-A-0-00-000-0-0
- Part No: LOC3-016-4-D-D-0-00-000-0-00-Z
- Part No: KIT EBV 10-40 D22
- Part No: OD10652
- Part No: 1720071
- Part No: OD31356
- Part No: PARKER508
- Part No: B8T-10
- Part No: FK-B8T
- Part No: P/N: 20214122723 Type: VGU/F.25/250.7.TS2.3
- Part No: OD30177
- Part No: SBV 1-40/13
- Part No: IHP 1,5 - 200/80/90
- Part No: P/N: 19029801747, Type: KIT EHV 2.5-350
- Part No: P/N: 19030200240, Type: KIT EHV 10-350
- Part No: DI10EYS/2/350CV24VCC
- Part No: DBD-S10K13/350/VC
- Part No: PWO B12Hx80
- Part No: EBV 10/40 PTFE-EVV
- Part No: PWO-B45-180
- Part No: 109650225 oem
- Part No: 10239601626
- Part No: Type: LOC3-016-4-4D-C
- Part No: ULAC-044F-M100SA
- Part No: LOC3-016-4-D-C-0-00-000-0-00-0
- Part No: P/N: 11076701125 Type: EHV ACCU 50-330/90 VALVE A
- Part No: 54780
- Part No: 99317 E
- Part No: 86220 E
- Part No: model FA-040-110V
- Part No: EHP-C-0010-250-080-AF00AA000
- Part No: Type: 2SIFI 80-4B2
- Part No: Skin Bag for IHV 50-300/85
- Part No: Leather Bag for IHV 20-300/85

- Part No: 539033
- Part No: 10876301120
- Part No: 19001000220
- Part No: 4556500223
- Part No: 20149203625
- Part No: DA-0.75L-210BAR-10849801125
- Part No: CWA4PNSBC
- Part No: 10837001125 / EHV 10-330/90-A25GA-200
- Part No: 19029900280
- Part No: HY10-4001/UK
- Part No: F1801-11066905200
- Part No: LOC-016-4DD-000-000-000
- Part No: 1380100
- Part No: 1380101
- Part No: 92700
- Part No: 10429-01125
- Part No: 109.104-01125
- Part No: 20214000200
- Part No: 1720044
- Part No: 1720030
- Part No: 3980C105
- Part No: 1010000000000000
- Part No: 108.706-600080
- Part No: T5861208
- Part No: 1720031
- Part No: 1720137
- Part No: LOC3 023-4-D-C-0-00-000-0-00-0
- Part No: LOC3 016-4-D-B-0-00-000-0-00- 0
- Part No: 20138106121
- Part No: EHV 10-330/88
- Part No: QPM 20-0.75-575V
- Part No: 10849301102
- Part No: OD10019
- Part No: 11059900220
- Part No: POS No35 /200148-04600

- Part No: SST-1
- Part No: 1720013
- Part No: K539058
- Part No: OD30227
- Part No: 323703
- Part No: REF 107188 01125 TYPE IHV 10-330/05 obsolete/ replaced by 10837001125
- Part No: 10849701102
- Part No: 2.5-350 / 90
- Part No: EHV 2.5-350/90 D22.5
- Part No: EHV2,5L-350B/90
- Part No: 1QT-100-3
- Part No: SP-907008 / GR32-SMT16B-75L
- Part No: 1720114
- Part No: PWO B8THX-20/1P-SC-M
- Part No: PWO B25T
- Part No: 1-ST1 8061A4
- Part No: 304L
- Part No: p/n: 19029400225; Type: KIT EHV 24.5-330/90-A25GA
- Part No: p/n: 19029900225; Type: KIT EHV 4-350/90-A25DC
- Part No: PARKER2051
- Part No: WEGO3
- Part No: 111270-00280
- Part No: AL71 1024428114
- Part No: 10866101125 / EHV 4-350/90-A25DB-200
- Part No: EHV 10-330/90-A25GA-200 10837001125
- Part No: EHV 4 330/90
- Part No: ELM 0,5-210/00 -108495-01125
- Part No: DA-050-21000AF1102P000
- Part No: PARKER3078
- Part No: OLG-1 20/00 obsolete
- Part No: EHV10-330/90K-330-AA25-13-00
- Part No: 172383
- Part No: 50-100-200
- Part No: 10887901102
- Part No: EHV 32-330 D22

- Part No: EHV10-330/90K-330-AA25-13-000
- Part No: PWO B120T-60
- Part No: PWO B120TH-30/1P-SC-S 4XSAE-2"
- Part No: 508454
- Part No: EHV 20-330/94 old code / EHV20-250/330D50 new code
- Part No: EHV20-250/330D50
- Part No: 10837101125
- Part No: 1720068
- Part No: F120-RF-05400001
- Part No: C404993
- Part No: F120-C-00247512
- Part No: DA-0.5L-210BAR
- Part No: EVH 32-330
- Part No: 108698 00225
- Part No: S/N: 111087172001929
- Part No: 50831002
- Part No: Repair kit for DI20 FS 2-3 330.B4.24V
- Part No: 110158-00225
- Part No: Gas valve assembly for EHV-50
- Part No: 19029000280
- Part No: Oil part assembly for EHV-50
- Part No: Bladder for EHV-50
- Part No: EBV 475-10/90-X25X-H200
- Part No: BOL-1134 Code 012410
- Part No: EHV 5-350/90 U2
- Part No: 110086-00200
- Part No: E226
- Part No: EHV12-350/90
- Part No: APD300-0-0334
- Part No: BA05B3L01P2
- Part No: 19036900225
- Part No: 042786011S1 / SBV2 ACCU 2.5-40/11
- Part No: 1720176
- Part No: EHV 1-350/90-350-AA80-11-002
- Part No: 109866-01125

- Part No: EHVF 12.330/90
- Part No: bladder kit for EHVF 12.330/90
- Part No: 108505-01125
- Part No: Bladder accumulator for ECA-12-01-L-N
- Part No: DA-140-14090AF1102P000
- Part No: 10850501102
- Part No: GR70-SMT16B-800L-RF2+TEST
- Part No: PARKER2345
- Part No: ULAC-016B-0 000SW
- Part No: ULAC-016B-0-00SW
- Part No: 19029700225
- Part No: 108495-01125
- Part No: 10845601125
- Part No: VG107741
- Part No: VG-3-25-TT52
- Part No: PWO B120T-80
- Part No: EHV 2.5-350/90-A25DB-200
- Part No: 11810201125
- Part No: set of rubber balloon with gas valve for Typ:IHV20-330/90
- Part No: gasket set for Typ: IHV20-330/90
- Part No: 1102/1316457-001-3 discontinued
- Part No: SAC 044-6A-T02-DSG-S OEM
- Part No: IHV - 1350/90
- Part No: LOC3-007-4-D-A-0-00-000-0-00-Z
- Part No: OLMO.75-210/31
- Part No: Gas valve kit for EHV 20-330/90
- Part No: FCHU221321-C
- Part No: repair kit for IHV 4-330/38
- Part No: EHV 24,5-330
- Part No: Repair kit for IHV4-330/05
- Part No: VGU 25/250.8.TSG.3.2
- Part No: 508478 / PWO B25-40 old code, new code 1720128 / PWO B25TH40
- Part No: 1720128/PWO B25TH40
- Part No: 5849044433 / LOC3-044-4-B-D-0-00-000-0-00-0
- Part No: 20213900803 / VGU/D.SM.8.STS.3

- Part No: F1801 108 368 05200 05
- Part No: MBSP 0.16-250
- Part No: 190302-00225
- Part No: 10883701125 / EHV 20-330/90-A25NA-200
- Part No: 10876401125 / EHV0,5L-350B/00 AMIX25
- Part No: 1-350/90 108669-01125
- Part No: LOC2F-023-4-D-B-0\_FPE22-80
- Part No: 539003 / LD 003
- Part No: LAC2-M-007-4-X-00-000-0-Z
- Part No: LAC2-M-016-4-X-00-000-0-Z
- Part No: RAO01441 (IBV 50.16)
- Part No: GR32-SMT16B-45L-S2-G-RF2-TM
- Part No: FPO K030-20M
- Part No: LAC-033-6-A-00-000-0-0 (5826033019)
- Part No: SPARE PARTS KIT FOR 11MBU41AA010
- Part No: 508489 / PWO B35Hx090
- Part No: GR60 SMT 440L SN
- Part No: 293607
- Part No: 1720088
- Part No: 051094 NO:061268
- Part No: Valve Nut for EHV 10-330/90-A25GB-200
- Part No: Gas Valve Assembly for EHV 10-330/90-A25GB-200
- Part No: Gas Valve for EHV 10-330/90-A25GB-200
- Part No: Gas Valve Plug for EHV 10-330/90-A25GB-200
- Part No: Fluid Port seal for EHV 10-330/90-A25GB-200
- Part No: Back up seal ring for EHV 10-330/90-A25GB-200
- Part No: Back up ring for EHV 10-330/90-A25GB-200
- Part No: Bladder for EHV 10-330/90-A25GB-200
- Part No: 19035800225 / KIT EHV 10-330
- Part No: VAR
- Part No: 35128811002 / DI 16 MS/1/
- Part No: 108655-01125 / EHV 20-330/90
- Part No: 10865501125 / EHV 20-330/90-A25GB-200
- Part No: VGU/F.25/400.8.TS2.3
- Part No: E702986

- Part No: VGU/F.25/250.8.TS8.3
- Part No: GCD-016P
- Part No: EHV32-300 G2 ASME
- Part No: EHV50-300 G2 ASME
- Part No: EHV20-300-G2 ASME
- Part No: Model No. K16-20
- Part No: 10849701125
- Part No: FCHX233218-B / 54L
- Part No: FCHX233218-B / 20L
- Part No: 110670-05200
- Part No: 2000A-00-341
- Part No: PARKER2940
- Part No: PARKER2939
- Part No: 508312006 / PWO B120THx100/1P-SC-S 2x1
- Part No: 35172111H02 / DI10MS/1/250CV
- Part No: EBV 300-20/90-A25PA-200
- Part No: LAC-110-8-A
- Part No: 539110 / LD 110
- Part No: 9300000000000
- Part No: EBV20 40/90
- Part No: 10859701125
- Part No: PWO K16-60
- Part No: W268SA-W6-08F
- Part No: W25SA-4G-Q8F
- Part No: EHP-C-050-250-200
- Part No: K508480
- Part No: LAC2-X-023-4-D-00-000-0-
- Part No: GR60-SMT16B-500L
- Part No: EHV 1-350/00-A25BC-200
- Part No: R901290399 / EHV 20-300/94-3000-A&
- Part No: PWO B35-40 (508484)
- Part No: EHV12-330/90 01125
- Part No: DA-140-21090AF1102P000
- Part No: 20138105121 / VG3.250.1.TS2.1
- Part No: 20270749999

- Part No: PARKER3083
- Part No: impeller for SAC 110-6-A-000-ESF-S
- Part No: 040SA-W6
- Part No: DI20EYS3210CV
- Part No: LAC-110-6-A-00-S50-0-0
- Part No: OSA32-M-CAV-30-210
- Part No: PARKER3132
- Part No: 108840-93440
- Part No: DI 16 MS9/200 CH
- Part No: LOC3-007-4-D-A-0-00-S25-0-00-0 / 5849007003
- Part No: IHV 4,0-330
- Part No: IHV10-330/90-L
- Part No: IHV4-350/90-L
- Part No: OLM2-100/9
- Part No: bladder kit EHV 2.5-350/90 01125
- Part No: repair kit to EHV4 - 250- 330/90
- Part No: PARKER2345 ELM-3,5-250/90/AF
- Part No: PARKER120