

ENDURA SUPPLY

Resatron Product List

- Part No: 02.05.25131400, RSM 58-13+12-G-3-W1-SS
- Part No: 02.12.25231459
- Part No: 02.41.2530302100 RSH 75 I 13 + 12 - 30 - 3 - C
- Part No: 04.09.02104031, RS KA 21 - ST 4 - 30 - RSM 58
- Part No: RS 98 EX-M 13+12-G-3-KS
- Part No: RS ST 1
- Part No: RS ST 5
- Part No: RSC 58-13+12-P-3-V6-US
- Part No: RSE 59-18-3-P-W1-DS-8
- Part No: RSF 58 P 26-3-B-W1N-DS4-F2 (02.12.26231981)
- Part No: RSF 58 P 29-3-B-V6-DS
- Part No: RSG10P02 - PROFIBUS DP
- Part No: RSM 58-12+12-G-3-V6-SS-F
- Part No: RSM 58-13+12-G-3-W1-KS
- Part No: RSM 58-13+12-G-3-W1-SS
- Part No: RSM 59-18+01-G-3-W1-KS
- Part No: 02.05.25131400
- Part No: RSP02- 58 13+12-3-B-W1-0S-F2 02.12.25231455
- Part No: RSP02 58-13+12-3-B-V6-DS - ABSOLUT WINKDEL CODIERER
- Part No: RSP02 58a "PROFIBUS DP
- Part No: RSP02-58 13+12-3-B-W1-DS-V
- Part No: RST 59-18+01-G-3-V1-SS
- Part No: RSM58-13-12-G-3-W1
- Part No: RSF 58 P 26-3-B-W1N-DS4-F2
- Part No: 02.01.241334000
- Part No: 04.10.12102001
- Part No: 02.12.26231981
- Part No: RSST4
- Part No: RSP02-58
- Part No: RSF 58 P 29-3-B-W1-DS 02.12.29231100
- Part No: RS GEL 500S - 10/10
- Part No: RSE 59-18-3-P-V6-DS8

- Part No: RS BSK 41 30 12
- Part No: RSF58P26+3-B-W1-DS4-F2
- Part No: RSF 58 P26-3-B-W1N-DS4-F2
- Part No: RSG 10 B 25 + 1250 - G - V1 - 2SS - H
- Part No: RSP02- 58 13+12-3-B-W1-DS
- Part No: RSG 10 P02 13+12-3-B-V1-DS
- Part No: RST 59-18+01-G-3-W1-KS
- Part No: 59-18+01-G-3-W1-K
- Part No: RSHF 58 P 29-B-3-2N-DS, Art N: 02.40.29233250
- Part No: 02.12.25231150
- Part No: Incremental Rotary Encoders
- Part No: RSR 58
- Part No: RSR 58 Incremental Encoder
- Part No: RSR 80 Twin Encoder with Different Pulse-Numbers
- Part No: RSL 58 Hollow Shaft Encoder
- Part No: RSH 58 Hollow Shaft Encoder
- Part No: RSH 76 Hollow Shaft Encoder
- Part No: RSH 120 Hollow Shaft Encoder
- Part No: RST 58 SSI Single-turn Encoder
- Part No: RST 59 SSI Single Turn Encoder
- Part No: RSTH 59 Single Turn Encoder
- Part No: RSM 58 SSI Multi Turn Encoder
- Part No: RSH 75 M SSI Multi Turn Encoder
- Part No: RSM 59 SSI Multi Turn Encoder
- Part No: RSMH 59 SSI Multi Turn Encoder
- Part No: RSC 58 SSI Multi Turn Encoder
- Part No: RSH 75 C Programmable Multi Turn Encoder
- Part No: RSE 58 SSI Programmable Multi Turn Encoder
- Part No: RSE 58 SSI Programmable Single-Multi Turn Encoder
- Part No: RSE 59 SSI Programmable Single-Multi Turn Encoder
- Part No: RSN 58 Electronic Cam Controller Encoder
- Part No: RSG10M1312B3V1SG
- Part No: RSH 75 I-13+12--30-3-C - obsolete
- Part No: RSH58-1024 DS1D-8R00
- Part No: RSE59-18-3-P-W1 DS

- Part No: RSN 58 12+12-P-3-V6-KS
- Part No: RSF-58 PN29-3-B-W1N-DS-F2
- Part No: 03.01.00103002
- Part No: Nr. 02.12.26231981 Type RSF 58 P 26-3-B-W1N-DS4-F2
- Part No: RSG 10 FEN 29-3-B-V1-DS
- Part No: RSG 10 FEN 29-3-V1-DS 02.22.29313300
- Part No: RSP02 58–PROFIBUS DP
- Part No: RSP02-58 13+12-3-B-W1-DS-V (OEM) obsolete
- Part No: RS KA 21
- Part No: RSF58P26+3-B-W1-DS4-F2 - not available, alternative RSF 58 P 26-3-B-W1N-DS4-F2
- Part No: 02.12.25231450, RSP02- 58 13+12-3-B-W1-DS
- Part No: RSW 10
- Part No: Nr. 02.40.29233250 Type RSHF 58 P 29-B-3-2N-DS
- Part No: RSW 10 with attached RSP02- 58 13+12-3-B-W1-DS
- Part No: Montage Seilzug Geber
- Part No: RSP2059B
- Part No: RSH 58 M-13+12-G-3-2-SS
- Part No: 02.40.29233100
- Part No: 02.30.25133230
- Part No: 04.07.7558
- Part No: RSP 02 58-13+12-3-B-V6-DS
- Part No: P/N: 02.01.251334400, Type: RSG 10 M 13+12-G-3-V1-SS-H
- Part No: RSP02- 58 13+12-3-B-V6-DS (02.12.25231150)
- Part No: RSP02-58 13+12-3-B-W1-DS (02.12.25231450)
- Part No: RS-DT-E-P-S-K-E-SO10T-N
- Part No: RSG 10 M
- Part No: 180817112
- Part No: RSF 58 PN-29-3-B-V6-DS
- Part No: RSF 58 P/N: 29-3-B-W1N-DS-F2
- Part No: 02.12.29131200 - RSF 58 P 29-3-B-V6-DS
- Part No: RSG 10R-1024-Y-3-G-V1-KS7-H
- Part No: RSOP02-58 13+12-3-B-W1-DS
- Part No: RSC0258-13+12-P-3-W1-UG
- Part No: 58-13+12-P-3-W1-US
- Part No: RSP02 58-13+12-3-B-W1-DS-F2

- Part No: RSHF 58P29-B-3-6-DS
- Part No: RSH 58-RSH 75
- Part No: RSF 58 PN 29-3-B-W1N-DS-FS
- Part No: 03.01.00103002 RSW 15