

# ENDURA SUPPLY

## Pacific Scientific Product List

- Part No: N31HRFL-LNK-NS-01
- Part No: 10-132-02
- Part No: 640-0041-003 obsolete
- Part No: 6410-001-C-N-K
- Part No: 6410-001-N-N-N
- Part No: 85906-2
- Part No: 85907-2
- Part No: APS4-C-PP WITH 13746254
- Part No: DMKL062F 85015190
- Part No: E32NRFA-LNN-NS-00
- Part No: E32NRLP-LNN-NS-00
- Part No: E41SSHS-LSS-NS-02 CLASS B oem
- Part No: EP3648-4952-7-56BC-CU
- Part No: FGS2438
- Part No: H32NRFP-LNN-NS-01
- Part No: K31HRHJ-LNK-NS-00
- Part No: K42HRHN-LNR-NS-00
- Part No: KOLLMORGEN PMA42J-1Y10B-64
- Part No: KOLLMORGEN P.P.SIGMA E22 NSFB-LNF-02 CAVO PREF."4 P.V.N.
- Part No: M21-NRXB-LNN-NS-00
- Part No: M22NRXB-LNN-NS-00 ALTERNATIV
- Part No: M22NRXD-LNN-NS-00
- Part No: M22NSXA-LNN-NS-02
- Part No: N31HRF-LNK-NS-001 PAC
- Part No: NSFB-LNF-NS-00
- Part No: OCE930-001-00
- Part No: P/N.EP3640-4524-17-56-C-CU;MDL INSUL.CLASS H DUTIES CONT
- Part No: P21NRXC LDN - M1 - 00
- Part No: P21NRXD-LNN-NS-00
- Part No: P21NSXB-LNN-NS-04
- Part No: P22NRXC-LNN-NS-00
- Part No: P22NRXE-LNN-NS-00

- Part No: PAC-SCI PMA44R-1050B-08
- Part No: PC833-001-N
- Part No: PC834-001-N
- Part No: PF501H-A-2-10 / 3648-495
- Part No: PMA 12 BRUSHLESS MOTOR
- Part No: PMA21J-1Y10B-15 obsolete
- Part No: PMA240-1050B-02 /NR
- Part No: PMA240-1050B-02,S/NR023304303 RATED (S1) 1.2 KW 3,4A ~ 8300 RPM 560/640V IP65I.CL. F
- Part No: PMA43N-Y0100-02
- Part No: PMA43P-01100-00
- Part No: PMA44R-1050B-08
- Part No: SC402-023-T4
- Part No: SCE903AN-002-01
- Part No: Spare Part for VDEO530-S1 EN60034-1
- Part No: FGS2434
- Part No: T21NRLH-LDN-NS-00 STEPPER MOTOR FOR P70530 DC DRIVE
- Part No: T21NRLH-LNN-NS-00
- Part No: T5-2002-101-00
- Part No: T5-2002-101-00 CABLE 10-150 LBS
- Part No: T60-1001-C9-1A
- Part No: VDE0530-S1 OBSOLETE
- Part No: VDEO530-S1 EN60034-1 obsolete
- Part No: VM 3352-000-29
- Part No: YP00583
- Part No: E589MGB
- Part No: 33VM52-000-14
- Part No: PMA240 -1050B -02 OEM and obsolete
- Part No: Model No: 5210 Date code: 49223
- Part No: SCE903A3-002-01 OBSOLETE
- Part No: SBM 86 20 3 5 42K 2 54 S F
- Part No: F.W. BELL 5180 (obsolete - replaced by 415180)
- Part No: T5-8002-104B-00
- Part No: SC402-012-T4(obsolete ne replacement)
- Part No: EP3648-4952-56BC-CU

- Part No: T60-1001-C8
- Part No: E33NRFC-LNN-NS-01
- Part No: H33NRHB-LNN-NS-00
- Part No: SK24N-1040-000
- Part No: P22NRXB-LDN-M1-00
- Part No: M22NRXA-LNN-NS-00
- Part No: 33VM52-008-4 Obsolete
- Part No: PC833-001-T
- Part No: P21NRXB-LNS-NS-07 OEM
- Part No: SC752A-001-01 Obsolete
- Part No: 6410-001-NNN
- Part No: CV6410
- Part No: CK6410
- Part No: 6410-001-C-H-K
- Part No: HS6410
- Part No: H33NRFP-LNN-NS-00
- Part No: H32NRFA-LDN-NS-00
- Part No: T60-1001-C8-1A
- Part No: 33VM62-220-1 OEM
- Part No: E33NRFC-LNN-NS-00
- Part No: HAD61-2508-05-T
- Part No: PMA24D-00100-00
- Part No: FGS2819 oem
- Part No: T23NLLC-LNN-NS-00
- Part No: EP3756-4553-7-56BC
- Part No: FGE0235
- Part No: SRF5570-4986-84-5-82BC-CU
- Part No: brush bridge assembly for SRF5570-4986-84-5-82BC-CU
- Part No: VTC15372516
- Part No: R65gena-R2-Ns-Nu-Oo
- Part No: H32NCHA-LNN-NS-00
- Part No: M22NRXB-JDN-M1-00
- Part No: R43HSNA-HS-NF-NV-02
- Part No: 6410-001-C-N-N
- Part No: T21NRLH-LDN-N8-00

- Part No: OCE950
- Part No: P21NRXC-LNN-NS-00
- Part No: M22NRXB-LNN-NS-00
- Part No: E32NLFA-LNN-NS-00
- Part No: T5-2002-104-00
- Part No: E33NCHP-LNN-NS-00
- Part No: E22NSFB-LNF-NS-02
- Part No: SR3632-4010-7-48P oem
- Part No: connector for M22NSXA-LDN-M1-02 OEM
- Part No: BA3638-4588-9-56-BC
- Part No: diaphragm for BA3638-4588-9-56-BC
- Part No: check valve for BA3638-4588-9-56-BC
- Part No: PMA21B-12000-02 obsolete
- Part No: K42HMHM-LNK-NS-00
- Part No: E43HMHB-LNK-NS-00
- Part No: PMA41B-1Y10B-64
- Part No: E32NRFP-LNS-NS-02
- Part No: 45402 // PN 13083-5
- Part No: PMA55R-10100-00
- Part No: 05167 19998908
- Part No: 45402 0101716-05
- Part No: E32NRFP-LNN-NS-04
- Part No: 05167 14003110.
- Part No: E32NRFA-LDN-NS-00
- Part No: S32GNNA-RNNE-00
- Part No: 6331
- Part No: TS-8008-106-00
- Part No: PMA42I-Y0Y00-05
- Part No: N-33HLLG-LNK-NS-00
- Part No: H32NCLT-LEN-M2-00
- Part No: T5-8008-106-00
- Part No: K32HRHJ-LNK-NS-00
- Part No: 6410-001-C-N-N Option H
- Part No: 6410-001-C-N-N Option K
- Part No: E31NSHS-LNN-NS-04 / pn: E31NSHS-LNN-NS-AO

- Part No: P21NRXD-LNF-NS-00
- Part No: E33N RFA-LNN-NS-00