

ENDURA SUPPLY

PNEUMATIC UNION Product List

- Part No: 110 310 2 02401
- Part No: Typ ZDP 100/250 / Nr. 1651289
- Part No: PL 40N1EX0075
- Part No: 106.462.4.33.021
- Part No: 336120822011
- Part No: 200 206 8 - obsolete, replaced by 336120822011
- Part No: 60411625 - obsolete, replaced by 60411615
- Part No: 60411615
- Part No: 2002079
- Part No: 290605204060
- Part No: 290604606102
- Part No: A⁶ - 1/4 60460613
- Part No: 60413630 obsolete
- Part No: 107077422021
- Part No: 60413330
- Part No: TRAL106436021
- Part No: DTR0024389ACU
- Part No: DTR0024389ADP
- Part No: 106 660 22021
- Part No: DTR6-1/460460613
- Part No: 60411611 old ref, new ref is 60411911
- Part No: 60411911
- Part No: 60520406
- Part No: CS20E1XXD160DM
- Part No: 336000000000
- Part No: 60411615 - not available; alternative - 60411315
- Part No: 291000000000
- Part No: Ø6 - 1/4 60460613
- Part No: 107000000000
- Part No: CS 20E1XXD0160 DM
- Part No: 2501992
- Part No: 101 0438 02401

- Part No: 64361217
- Part No: 60411315
- Part No: 60411610
- Part No: PL 40N1FC0075
- Part No: D63N1FC140
- Part No: 64365010
- Part No: PAIT50N1FCT150
- Part No: kit for PX Ø 40 (6062826M)
- Part No: 332000000000
- Part No: 247000000000
- Part No: 2996263.1I old code- new code 299626300000
- Part No: 300000000000
- Part No: 60411910
- Part No: 1094636 obsolete
- Part No: repair kit for 1094636 obsolete
- Part No: seal kit for PC125-1FZ0300 (243782940000)
- Part No: 33608221
- Part No: 1097019-024-23
- Part No: PX63 AXX 500 DN/NP4
- Part No: 60803905
- Part No: PX 63A1XX0500 DM/MP4
- Part No: P/N DTR0024389ACU
- Part No: PC100A1FC0200
- Part No: 60511561
- Part No: 211092 02423
- Part No: base plate for ISO T1 60471171
- Part No: 100347
- Part No: POCHETTE JTS PSP/PST D80
- Part No: Seal kit for PSP 80A1GX320 / DM X6356
- Part No: 60280810
- Part No: 61510610
- Part No: 60780405
- Part No: 60940606
- Part No: 60540720
- Part No: 60720404

- Part No: 60430606 | 290604306060
- Part No: 60411623
- Part No: 200 206 7 (110VAC 50Hz)
- Part No: 106 462 4 22021 S
- Part No: 3312535 -502 1/4 T0606
- Part No: 3312535 -502 1/4 T0606 (with two cores and two coils)