

ENDURA SUPPLY

Poclain Product List

- Part No: MS83-2-111-A83-4220-5CJM0
- Part No: 000250396U GLACE-MS18-2C-CAST-SY-PAP
- Part No: 000350899M B-BCYL-MSE18-T60
- Part No: 001150828A B-PISTON-E-50
- Part No: 001443889U
- Part No: 002843892M MK18-0-121.F12-1340-DP00
- Part No: 002943810T UNKNOWN PART #
- Part No: 003143725S MS05-0-113-A05-2A10-0000
- Part No: 005943896G
- Part No: 005949678R
- Part No: 006149648A KITSAV-FULL-SEAL-MK18
- Part No: 006946238J B-CAME-MS18-0
- Part No: 007246297K B-CAME-MS18-1
- Part No: 007546299Z B-BCYL-MS18
- Part No: 5816250
- Part No: 0C 056-257+257
- Part No: 001343822B
- Part No: 859.S150164
- Part No: A02551X B-PAL-MK18/MKE18
- Part No: A18801L KITSAV-DISTRIB-SEAL-MS18-SYM
- Part No: A77703
- Part No: J918944
- Part No: KWEWKY 43J10/24 VOLT
- Part No: MK08-9-124-F08-1340-A000
- Part No: MRP 2-10
- Part No: MS05-8-113-A05-2A10-0000
- Part No: MS08-0-111-R08-2A10-E000
- Part No: MSE02-2-123-F03-1120-DJ00 obsolete, replacement MSE02-2-123-F03-1120-YDJ0
- Part No: MSE05-B-B7A-F04-2ACO-DFMTV
- Part No: MSG•18-1-121-F19-1210-000MR
- Part No: P/N 004243871D
- Part No: P/N 004243871D REV 20819

- Part No: REPAIR KIT MK08-8-124-F08-1340-8A00
- Part No: REV 20819 L /N 069BK
- Part No: SPARE PARTS FOR HYDRAULIC MOTOR SERIAL N 005643865L (OBSOLETE)- replaced by 05816250
- Part No: V/6MC/4215
- Part No: VB-110-570-43-C5-504-0000
- Part No: KITSAV-FULL-SEAL-002-MS18-JR-M
- Part No: WASHER-SPRING-C225-112-6.5.
- Part No: MS02-2-123-F83-112E-235OHJ - Obsolete Replaced with "MS02-2-123-F03-1120-Y23DHJ"
- Part No: MS02-2-123-F03-1120-Y23DHJ
- Part No: MS35-1-A21-A18-1310-2DEJ - Obsolete Replaced with "MS35-1-A21-R18-1310-25DEJM"
- Part No: MS35-1-A21-R18-1310-25DEJM
- Part No: MSE02-1-123-F03-1120-J000,003743830F ,Ser a,,– UP00039511
- Part No: MSE02-9-12A-F03-1130-YDJV
- Part No: PISTON AND ROTOR FOR ROUL : 3122/ 1561X 55419.86 CODE : 1151010011
- Part No: A10859D,OF:VP00037868027, MSE05-0-16A-F04-1230-9DEFJF... OEM
- Part No: HMS18 - 8 - A21 - F12 - 1120
- Part No: 005643865L
- Part No: MS11-0-G21-F12-1320-0000
- Part No: 004349686U
- Part No: Rotor for MC08-22-1041-F08-111-1000 OBSOLETE
- Part No: Valve piston for MC08-22-1041-F08-111-1000 OBSOLETE
- Part No: KIT-J-T-MK08-FPM
- Part No: 003743809H obsolete replacement MSE02-2-12A-F03-1120-YJ00
- Part No: MSE02-2-12A-F03-1120-YJ00
- Part No: 005949694J
- Part No: 003540407T
- Part No: F08 - MSE08
- Part No: MSE05-2-113-R05-0000-DH00
- Part No: MS11-2-D21-F11-1110-G000 obsolete
- Part No: MS25-1-121-R25-1120-E000
- Part No: PMV-018
- Part No: MS 18 0 A21 R18 7221 5M00
- Part No: MS18-0-A21-R18-7221-58GM
- Part No: A22083D

- Part No: VB-220
- Part No: MSE05-2-133-R05-1220-DEJ0
- Part No: mc08-22-10a1-f08-111-0000 OEM
- Part No: MSE02-2-123-F03-1120-YDJ0
- Part No: 5818233
- Part No: 005643863J (alternative is MK04-2-114-K04-3340-3590)
- Part No: 05546244 obsolete alternative 05800984
- Part No: 5800984
- Part No: MK04-2-114-K04-3340-3590
- Part No: MS05-2-14A-F05-8AD0-56EF (B21209C)
- Part No: 1213695
- Part No: MSE08- 0-111-A08-2A50-EJ00
- Part No: 00233BASMSE08
- Part No: MK 11 (003343823Q) obsolete, replaced by MK 11 (005043833C)
- Part No: MK 11 (005043833C)
- Part No: MKD04-2-114-K04-3340-37MZ
- Part No: A27257C
- Part No: A27256B
- Part No: 002639862Q
- Part No: 002639878H
- Part No: 009246217L
- Part No: 006327890R
- Part No: 009030158P obsolete, replaced by B28539U
- Part No: Seal kit for MS11-2-G21-C12-1720-8EJA obsolete, alternative A27041S
- Part No: Seal kit for MS11-2-D21-C12-1720-8EJA obsolete, alternative A21689A
- Part No: MSE-0-15A-F03-1120-DJOO
- Part No: 000850883X obsolete, replaced by A27041S
- Part No: A21689A
- Part No: A35614L
- Part No: B28539U
- Part No: A27041S
- Part No: MHP20-222-A11-O-FT30-Y000 oem
- Part No: MS35-2-A21-F19-1G20-5GJMP
- Part No: MS18-2-A21-F19-1G20-5EGJMP
- Part No: MS18-2-D21-A18-1220-8J00 obsolete

- Part No: A49777F
- Part No: A46661T
- Part No: 007142237B
- Part No: A16271L
- Part No: A16929B
- Part No: A42959U
- Part No: B20253N
- Part No: KITSAV-FULL-SEAL-MS02-MSE02-6V (inkl. 9200,9100,9350)
- Part No: KITSAV-FRE-DISK-F03 (9210)
- Part No: FRE-PISTON-F02-D140 (2305)
- Part No: CFRE-F03-1C-G (2005)
- Part No: WASHER-SPRING-C140-72-3.8 (2040)
- Part No: INNER-SNAP-RING-140 (2080)
- Part No: MS83-M-C11-F60-4220-7000
- Part No: MS83-A-C26-F83-1320-7CJ0
- Part No: Repair kit for MK04-2-114-K04-3340-3590
- Part No: PO-005949675N
- Part No: PO-006349624Q
- Part No: PO-006149633J
- Part No: PO-A28561U
- Part No: MK08-8-124-F08-1340-8A00 (Obsolete - OEM)
- Part No: VB-002-003-M4-504-0000
- Part No: 005549601A
- Part No: MK04-2-11A-K04-3340-3F00 obsolete
- Part No: MS18-2-G21-F19-1220-8DEFGJ, Cod:A09147S replacement by MS18-2-G21-F19-1C20-8DEJ
- Part No: Rotor for typ MC08-99-1041-F08-111-F00, Cod:008143738P
- Part No: Stator for typ MC08-99-1041-F08-111-F00, Cod:008143738P
- Part No: Roller for typ MC08-99-1041-F08-111-F00, Cod:008143738P
- Part No: Plunger piston for typ MC08-99-1041-F08-111-F00, Cod:008143738P
- Part No: Seal for typ MC08-99-1041-F08-111-F00, Cod:008143738P
- Part No: 005649658H
- Part No: MS18-2-G21-F19-1C20-8DEJ
- Part No: POS-SENSOR-RS52-5VDC-22A
- Part No: 1067062 OEM
- Part No: MK04 - 2

- Part No: MS05 - 0
- Part No: MSE05-2-G24-F04-1720-J000
- Part No: MS18-2-121-F19-1120-E000
- Part No: NS35-2-DB1-R35-2A10-5EJ0
- Part No: 70765512
- Part No: AO8747H
- Part No: ESE02-1-1442-F02-21114-D0 obsolete
- Part No: MK04-0-114-K04-3340-3000
- Part No: MS11-0-122-A11-1320-G000
- Part No: 004243871D
- Part No: MS?18-1-121-F19-1210-000MR
- Part No: POS : 013 İÇİN AYRI BİR EKSEN YOK!
- Part No: A30273F, KITSAV-FULL-SEAL-MK08
- Part No: SPARE PARTS FOR MSB 02-2-123-?02-1240-?000
- Part No: VB-110-560-41-C5-504-1000
- Part No: VB-110-560-41-C5-504-1000 / R00250007W
- Part No: 003643741N Type MS11-0-122-A11-1320-G000
- Part No: 1-362029 MC08-88-1041-F08-111-1000 002243845M - Obsolete!!
- Part No: MSE02-1-123-F03-1120-J000,003743830F ,Ser ? UP00039511
- Part No: MS25-1-121-R25-1120-E000 (007343750M)
- Part No: ERSATZTEILE FÜR MS11-2-D21-F12-1720-J000
- Part No: MKD04-2-114-K04-3340-37MZ oem
- Part No: A13475W
- Part No: MK05-2-124-F04-1340-0000 (002343869J)
- Part No: KITSAV-FULL-SEAL-MK04
- Part No: 006349624Q
- Part No: MK08-8-124-F08-1340-8A00
- Part No: MS18-2-G21-F19-1C20-8DEJ / A28982C
- Part No: POS-SENSOR-RS52-5VDC-22°
- Part No: MS05-0-113-F04-2A50-J000
- Part No: PM Pump
- Part No: MS35-2-DB1-R35-2A10-5EJ0
- Part No: KV-4/3-5KO-10-R6
- Part No: A03657A
- Part No: MC08

- Part No: ML06-2-E6A-K05-3141-HZ00 OEM
- Part No: MSE18-2-G24-F19-1840-5F-J0 oem
- Part No: MC08-22-1041-F08-111-0000 obsolete
- Part No: ROTOR assy 9300 for MC08-22-1041-F08-111-0000
- Part No: 2410 for MC08-22-1041-F08-111-0000
- Part No: BREAK DISK 2405 for MC08-22-1041-F08-111-0000
- Part No: PLATE 4105 for MC08-22-1041-F08-111-0000
- Part No: Set of balls for MC08-22-1041-F08-111-0000
- Part No: Set of separator for MC08-22-1041-F08-111-0000
- Part No: Seal kit (for whole pump) for MC08-22-1041-F08-111-0000
- Part No: MSE02-2-123-A02-1L28-J000 obsolete, replacement MSE02-2-123-R02-1L2H-YJ00
- Part No: MSE02-2-123-R02-1L2H-YJ00
- Part No: Seal kit for MS18-2-121-F11-1330-0000
- Part No: Distributor for MS18-2-121-F11-1330-0000
- Part No: 006543771U Type MS05-0-113-F05-2A50-0000
- Part No: 005649614K
- Part No: MS08
- Part No: MS11-01-122-A11-1320-0000
- Part No: A30657X oem
- Part No: MK04-2-114-K04-3340-3000
- Part No: MSE02-2-11A-F03-3AC0-Y3FM
- Part No: Dichtsatz A31888L, KITSAV-FULL-SEAL-MS02-MSE02-6V
- Part No: 2x A32704X - KITSAV-FULL-SEAL-MK05
- Part No: B08372Z (pos. 1400)
- Part No: A07609V (pos. 1700)
- Part No: A17467L (pos. 9400)
- Part No: A17232F (Pos. 9200)
- Part No: 002343869J Type MK05-2-124-F04-1340-0000
- Part No: 291
- Part No: MK05-0-124-F04-1340-0000
- Part No: 001730033V
- Part No: 005543161A
- Part No: 000834924B
- Part No: MF01
- Part No: Freewheeling valves

- Part No: SmartDrive CT
- Part No: A06226S / MS11-2-D21-R11-1212-5EJ0
- Part No: VB-002-003-00-M4-504-E000
- Part No: MK08-2-124-F08-1340-1A00 OEM
- Part No: MS08-0-12A-R08-1230-5DEJ (007743729W)
- Part No: A5072337
- Part No: R00250007W
- Part No: MK08-8-124-F08-1340-A000 obsolete
- Part No: MK08-22-1041-F08-111-0000 obsolete
- Part No: 002243845M - MK08-8-124-F08-1340-1AP0 OEM
- Part No: MS02-2-123-R02-1120-YHJ0
- Part No: 003143535L / 6H14 FOL 32 473
- Part No: MS02-1-12G-F03-1J3A-Y7DFJM
- Part No: A24571H
- Part No: MK 47
- Part No: KITSAV-FRE-REP-F83
- Part No: B-BCYL-MS05-T56 / PN 009346242J
- Part No: MHP20-888-A11-0-2A50-YEJ0
- Part No: VBM-VFR-2EA-591-84-EB-314X , A07684C
- Part No: 000250803M, B-BCYL-MSE02
- Part No: A31888L, KITSAV-FULL-SEAL-MS02-MSE02-6V
- Part No: KITSAV-FULL-SEAL-MK05
- Part No: MS18-1-121-A18-1320-5000
- Part No: MS11 0 121 A11 1130 00 (code S41437.19)
- Part No: AS 80,00x120,00 H=12,00 NBR
- Part No: 95x140x52/87
- Part No: 003843887N
- Part No: A32704X
- Part No: MSE05-2-113-A05-2A40-0000
- Part No: bearings for MS11-2-G21-F12-1920-8DEJ
- Part No: sealing for MS11-2-G21-F12-1920-8DEJ
- Part No: cuff for MS11-2-G21-F12-1920-8DEJ
- Part No: repair kit for MS11-2-G21-F12-1920-8DEJ
- Part No: PO-002946192H
- Part No: MS35-2-1B9-R35-2A50-5EJM

- Part No: MS35-2-1B9-F42-2A50-5EJM
- Part No: KV-4/3-3KO-6-2
- Part No: old PN MS06-2-D1A-R06-2A10-5E00 / new PN MS08-2-D1A-R08-2A10-5E00
- Part No: MS08-2-G1A-F08-2A10-5E00
- Part No: 101650142443 BW 138 AD (SN1,S19,FS13,E1,E16,AG6)
- Part No: MS08-2-D1A-R08-2A10-5E00
- Part No: Brake disc for HW F1 TRAV00002A
- Part No: Cover for HW F1 TRAV00002A
- Part No: Brake caliper for HW F1 TRAV00002A
- Part No: KITSAV-FULL-SEAL-MS02-MSE02-NG (A36747S)
- Part No: A13941D (OBSOLETE)
- Part No: VB-010-040-00-C0-004-0000
- Part No: MS05-6-113-F04-2A40-5DEJ
- Part No: 002843821K
- Part No: VB-110-550-41-C5-504-0000
- Part No: VB-110-550-61-C5-504-0000
- Part No: 002843867K
- Part No: MS08-2-12A-R08-1230-5DEJ (A03657A)
- Part No: Repair kit for MK04-2-114-K04-33103500
- Part No: repair tool for A13953F
- Part No: 005643870R
- Part No: MT 50 - 00 -G210-F50
- Part No: MSE02-2-11A-F03-3ACO-M000
- Part No: Repair kit for MSE02-2-11A-F03-3ACO-M000
- Part No: (002343867G) MK05-8-124-F04-1340-0000
- Part No: KITSAV-FULL-SEAL-MK08 (A30273F)
- Part No: A31757T
- Part No: 000250805P / 3505
- Part No: A36711D / 3010
- Part No: 002639846X / 1205
- Part No: A05291B / 1305
- Part No: 000930255W / 4105
- Part No: KV-6/2-6-12DC-1/2-S50
- Part No: KV-8/3-6-12DC-3/8
- Part No: KV-6/2-6-RA-G3/8-YZ-S50 (YZ PLUGGED)

- Part No: MSE05-2-133-F05-1220-J000
- Part No: MS125-2-1BJ-R83-0001-YD
- Part No: MS125-2-111-A83-0001-D000
- Part No: VB-010-070-00-C0-00A-4ELO
- Part No: MS02-2-113-R02-2A50-YJ00 (A31410R)
- Part No: MS35-2-1B9-A35-0000-D000 (006743773N)
- Part No: MS 25-2-121-A25-1120
- Part No: inchventil for Hydr.Pump SH300 (21491)
- Part No: MSE18-2-A21-R18-7221-5M00 (A21523U)
- Part No: 005949675N
- Part No: PMV018S1S00A020R2005G00BLVS00
- Part No: MK04-2-11A-K04-3340-3DFP (OEM)
- Part No: MS11-9-111-A11-2A50-67E0
- Part No: TS-4-250-N-A
- Part No: MS080121R08112057E0
- Part No: 4016022
- Part No: ML06-2-E6A-K05-3141-FH00 (OEM)
- Part No: MS11- 2-D11-2A50-0000
- Part No: V1-15-S2-M-300R
- Part No: 90R100SB2BC60S3C7F33PEA424224
- Part No: P45435490 OEM
- Part No: A31429M MSE02-2-11A-F03-3AC0-YM00
- Part No: MSE03-2-D23-1120-5EJ0 (HYD416593)
- Part No: P/N: 7018180198, Type: PMV018D2N35AL15R1005F05VSES
- Part No: 006343737R
- Part No: P/N: B21888Q, Type: MS05-2-133-R05-1220-5DEJ
- Part No: MS05-0-113-A05-2A10-0000
- Part No: 8503895
- Part No: MSE02-2-123-F03-1120-YCJ0
- Part No: MSE02-2-123-R03-1120-YCJ0
- Part No: B73962S
- Part No: MSE08-1-111-F09-2A10-5EJO
- Part No: A47449A
- Part No: A22147X
- Part No: A50838J

- Part No: A52686S
- Part No: MSE11-2-121-R11-1220-257EJ / A39820H
- Part No: B58371V
- Part No: B61287Q
- Part No: MS25-0-011-A25-2A50-5000
- Part No: MS18-8-111-F12-2A50-E000
- Part No: MS25-2-121-A25-1120-0000
- Part No: 002743837-G
- Part No: MS18-8-111-F12-2A50-EJ00
- Part No: VB-220-340-42-05-504-5000
- Part No: 000250874P
- Part No: 007146250N
- Part No: MK05-2-124-F04-1340-H000 (002343869J)
- Part No: A18801L
- Part No: BOM05818455
- Part No: B02829Z-NS-500-C/450-O
- Part No: repair kit for A33700F SN: F00150154002
- Part No: 4H18 FOR 44 473
- Part No: MS18-02-D2A-R18-7221-5DMO
- Part No: MW14-4222-3G27-7721-5000
- Part No: MS18-2-D2A-R18-7221-5DM0
- Part No: MW24-2BM2-4D27-7221-5D00
- Part No: MS18-2-G2A-R18-7221-5DM0
- Part No: MW14-4222-3D27-7221-5D00
- Part No: MW24-2BM2-4G27-7221-5D00
- Part No: 7565060046
- Part No: 003643845B / MS08-1-11A-F08-0000-DF00
- Part No: gasket kit for B28524D
- Part No: B73747J
- Part No: 000836340Q
- Part No: B73742D
- Part No: 004349674G
- Part No: B76121P
- Part No: B70735K
- Part No: MKE 18

- Part No: MSE08-2-1XX-F09-0000-A
- Part No: MSE08-2-1XX-R08-0000-A
- Part No: roller assembly FOR MK-04-2-11A-K4-3340-3F00
- Part No: B39147A / KITSAV-FULL-SEAL-MK04
- Part No: old code MSE05-D-113-F04-4720-49DF, code:A03721U - new code: MSE05-D-113-F04-4720-49DFJ, code:A03721U
- Part No: MSE08-0-CC1-T09-2A40-8M
- Part No: MSE08-0-CC2-T09-2A40-8M
- Part No: PM50-52-S4-S-00-40-R-25-16-B-00-VS
- Part No: PM50-52-S3-S-00-40-R-25-16-S-00-VS
- Part No: 60192903 OEM
- Part No: stator for MSE5- D-113-F04-4720-49DFJ
- Part No: Rotary group for MSE5- D-113-F04-4720-49DFJ
- Part No: Distributor for MSE5- D-113-F04-4720-49DFJ
- Part No: Spring for MSE5- D-113-F04-4720-49DFJ
- Part No: Plastic block for MSE5- D-113-F04-4720-49DFJ
- Part No: Static frication for MSE5- D-113-F04-4720-49DFJ
- Part No: Dinamic frication for MSE5- D-113-F04-4720-49DFJ
- Part No: MSE05-D-113-F04-4720-49DFJ, code:A03721U
- Part No: MSE02-0-123-F03-1120-YJ00
- Part No: MS35-AVA-001
- Part No: MS018-2-111-E12-2A50-5EFJ/9100
- Part No: MS35-2-A21-T19-1120-5JPW
- Part No: MSE11-2-121-A11-1110-J000
- Part No: MSE05-2-133-R05-1220-EJ00
- Part No: A31387R
- Part No: 9100 seal kit for MSE08
- Part No: MSE-11-2-121-R11-1220-57EJ
- Part No: 7018130099 / PMV013S1N00A020R1005G000000
- Part No: 7018160051 / PMV016S1N00A025R1005F000000
- Part No: ML06-2-L3A-K05-3141-FH0 (OEM)
- Part No: A20618L
- Part No: A20619M
- Part No: KITSAV-FULL-SEAL-002-MS11-JR-M
- Part No: spare parts for MS35 MS35-9-1C9-A35-1110-0000
- Part No: MS11-2-121-A11-1320-G000

- Part No: B61288R
- Part No: MK08-2-12A-F08-1340-A000
- Part No: MS05-2-133-R05-1220-5BEF
- Part No: friction discs for MS18-2-114-F12-2A50-0000
- Part No: B79579X
- Part No: mke18-1
- Part No: F688810 780 CC OEM
- Part No: 002930495V 2560
- Part No: A46530B 2310
- Part No: 003540407T 2505
- Part No: spare part for MSE05-3-133-F04-1720-EJ00
- Part No: seal kit for MS05-2-113-R05-2A50-2500
- Part No: drive shaft for MS05-2-113-R05-2A50-2500
- Part No: 001430055H / ARB-M-MS05-DINM3Z50
- Part No: B76117K / KITAM-OPEN-MS05-212-107-26- NBR
- Part No: 005649633F / KITAM-CV-DISTRIB-MS05-NBR-1C/2
- Part No: A26471X
- Part No: B72972R / KITAM-PAL-REP-MS05-55-90- NRB75
- Part No: 002339852S / TAPER-BEARING-33211-C1
- Part No: A07691K/TAPER-BEARING-31310-C1
- Part No: MSE05-3-133-F04-1720-EJ00
- Part No: seal kit for MK04-2-114-K04-3340-3000
- Part No: seal kit for MSE05-3-11A-F04-APB-5DEHJ
- Part No: 004349661S
- Part No: MSE05-0-D1A-R05-2A10-5J00
- Part No: MS-18 (A 37441-W)
- Part No: TVTC -12-G1/2-G3/4
- Part No: B76139J / KITAM-OPEN-MS18/35-315-145-53
- Part No: A18801L / KITAM-CV-DISTRIB-MS18/35-NBR- 2