

ENDURA SUPPLY

Pauly Product List

- Part No: CVE /9MKOP
- Part No: CVS /4MKOP
- Part No: ET103/2000V /E2/Y/STA5/24VDC
- Part No: KABEL (STE4) /4MKOP/2STE4
- Part No: PP20110-2 /E2/2PG7/2PG11/Q/24VDC
- Part No: PP2441Q/308/R153E /E2, 4314qE (Empf.Lochsuchger.,Messweite;308mm gleichlichtfest bis 80 kLux , 3+1-pol.ger. Metallstecker)
- Part No: PP2441Q/308/R153S /R2/Z3S/115+230VAC
- Part No: (4314qS) PP2441q/308/R153S /R2/z3s/115+230VAC
- Part No: ET103/2000v /e2/y/stA5/24VDC Tester
- Part No: (4314qE) PP2441q/308/R153E /e2
- Part No: PP2441Q/308/R153
- Part No: PS20G19/y/ir/stH4
- Part No: PV2092/2E /e2/y/i/stH7/24VDC
- Part No: ET103/2000 /e2/i/stH4/24VDC
- Part No: PP83201/2
- Part No: STA5W
- Part No: 3153 E
- Part No: 3153 (3153E + 3153S)
- Part No: 3153S
- Part No: PP2841QE/308/R125
- Part No: 1885x10
- Part No: 1665Ex13
- Part No: PS20G19 /ir/stH4
- Part No: PV2092/2E/e2/i/stH7/24VDC
- Part No: stH7w
- Part No: JF19H
- Part No: P/N: 1721Ex01 Type: PV2092/2E /e2/y/i/stH7/24VDC
- Part No: PP2441qE/220/R28e2 - obsolete, alterantive - PP2441q/220/R28E /e2/1stLU5 (Ord.nr. 4313qEx03)
- Part No: PP83201/224VDC/R/z3 - obsolete, alterantive - PP2441q/220/R28S /2stLU5/24VDC (Ord.Nr. 4313qSx03)

- Part No: PP2441qS/220/R2824VDC - obsolete, alternative - PP83201/2 /R/e1/1M16/1M20/z3s/1stLU5/24VDC (Ord.Nr. 2420x19)
- Part No: PP2441q/220/R28E /e2/1stLU5 (Ord.nr. 4313qEx03)
- Part No: PP2441q/220/R28S /2stLU5/24VDC (Ord.Nr. 4313qSx03)
- Part No: 2420x19
- Part No: 4350CC2x01
- Part No: JP195 /R/d/rl/stH7/20...230VUC
- Part No: 1661Ex02 , type PP2092/2E /e2/i/stH7/24VDC
- Part No: 1884x05, type PS20G19 /ir/stH4
- Part No: PP2441Q/308/R153E/E2
- Part No: PP201Y0-2
- Part No: PP2441 (Q)/220/R28
- Part No: 431XT
- Part No: PP83201/2/ R/e1/1M16/1M20/z3s/1stLU5/115VAC (Ord.nr.2420x22)
- Part No: PV 2092/2E HD I E2 Y STH7
- Part No: 1102x36
- Part No: STH4
- Part No: STH7
- Part No: 4312qSx03
- Part No: 4312qEx03
- Part No: PP20110-2
- Part No: CvE /9mKSTS (3153Ex01)
- Part No: CvS /9mKSTS (3153Sx01)
- Part No: PP2441Q
- Part No: PP2441/308/R153
- Part No: PP2445/308S/e4/q/z3s/2stLU5
- Part No: PP2445/308E/e2/q/1stLU5
- Part No: PV1038/2 / R/2m20/i/fx/hz/45VAC
- Part No: JF57S
- Part No: Nr. 4354SX01, Type: PP2445/308S
- Part No: Nr. 4354EX01, Type: PP2445/308E
- Part No: PP2445CC2/5M/2STLU5
- Part No: PP83201/2 /R /e1 /1M16 /1M20 /z3s /1stLU5 /230VAC
- Part No: PP2445(Q)/308/R153
- Part No: PP2445/308
- Part No: Nr.4350CC2X01, Type: PP2445CC2

- Part No: PP2441 QS/308/R153 obsolete
- Part No: PP2441 QE/308/R153 E2 obsolete
- Part No: 4354EX02
- Part No: 4354SX02
- Part No: ET103/3000*1
- Part No: P/N: 4350AC1x01, Type: PP2445AC1
- Part No: P/N: 4350AC2x01, Type: PP2445AC2
- Part No: P/N: 4350CC1x01, Type: PP2445CC1
- Part No: JP195 D R STH7
- Part No: PP2441q/220/R28E
- Part No: PP2441q/220/R28S
- Part No: PP2445CC2
- Part No: PP2441qS/220/R28
- Part No: R26SH
- Part No: JP192-1REF
- Part No: JP191-1REF
- Part No: JP105RFZ
- Part No: PS20G19
- Part No: 1661EX01
- Part No: 4314QE PP2441G/308/R153E/E2
- Part No: 4314QS PP2441G/308/R153S/R2/Z3S/115=230VAC
- Part No: PP2445/308E /e2 /q /1stLU5 / 4354EX02
- Part No: 7911X01